

# MONUMENT RECORD

CORNER I.D.

0 - 21



STATE OF INDIANA - COUNTY OF MONROE

SECTION ~~#~~ 27, TOWNSHIP 8 NORTH, RANGE 2 WEST

## MONUMENT DESCRIPTION & REMARKS

PIPE PLACED FLUSH IN CENTERLINE OF PAVEMENT. IT WAS NOT  
CHECKED TO NORTH OR SOUTH, BUT WAS CHECK-CHAINED TO EAST  
AND WEST 2642.2' TO SW AND SE CORNERS OF SECTION 27.

### RECOVERY TIE DRAWING



(•) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, \_\_\_\_\_ HEREBY CERTIFY THAT THIS  
DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE  
WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF  
THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND  
THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL  
THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 19\_\_\_\_ A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:  
VAN BUREN

CORNER I.D.

0 - 21

SECTION 27TOWNSHIP 8NRANGE 2W

PSID002228

# 22# 28# 26# 34

NW, NW

NE, NW

NW, NE

NE, NE

SW, NW

SE, NW

SW, NE

SE, NE

NW, SW

NE, SW

NW, SE

NE, SE

SW, SW

SE, SW

SW, SE

SE, SE

2642.64

2642.64

Van Bu-OZI

## AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74

SURVEY PARTY

T. Daugherty - H. Sudbury

COMMENTS pipe placed flush in  $\pm$  of PVMT. - it was not checked to North or South, but was check chained to East & west 2642.2 Feet to SW & SE corners of Sec 27.

## REFERENCE SKETCH (use back if poss.)

